April , 2019

Scott Murphy, Municipal Manager Town & Village of Ludlow PO Box 359 37 Depot Street Ludlow, VT 05149

RE: Request for maintenance of road drainage and infrastructure

## **Background**

In August 2011, Tropical Storm Irene caused extensive damage throughout Vermont including the Town of Ludlow. In subsequent years, pursuant to the VTrans Better Backroads program, now known as Better Roads, the Town of Ludlow with the support of the Lake Rescue Association, applied for and received grants from the State of Vermont. These grants were for the purpose of making certain improvements to the roadways, infrastructure and drainage around Lake Rescue and Pauline to reduce sediment running off the roadways into the lakes and to improve lake water quality. Under the terms of the grants, funding for the initial construction was provided by both the State of Vermont and the Town of Ludlow and subsequent maintenance is the responsibility of the Town. Since the installation of the improvements many of the culverts, drainage basins and ditches along the roadways are filling in with sediment and need maintenance.

#### **Observations**

On October 8, 2018, two of our Board Members made observations on East Lake Road, Fishing Access Road, Ellison's Lake Road, Norman Drive, and Tepper Drive and observed that the drainage ditches, catch basins and drop outlets were clogged with sentiment and debris. More recently, it was observed that following the rain storm on Sunday, April 14, 2019 there was substantial erosion around the Lakes Region on roadways and streams draining into the lakes. Although we appreciate the quick response by Ludlow to re-grade East Lake Road after the storm, the cleaning and maintenance of the drop outlets, catch basins and drainage ditches is essential to reduce further erosion of roadways and the significant sediment entering the lakes.

### Request for maintenance to be performed

The Lake Rescue Association requests that the Town of Ludlow take action to clear and clean out the drainage ditches, drop outlets, catch basins and culverts on the local roads surrounding Lake Rescue and Lake Pauline.

#### **Information Attached**

Attached Exhibit A is a list of Road Segment Identification Numbers ("RSID#") for the road segments and the Object Identification numbers from the Atlas maintained by the Vermont Agency of Natural Resources ("ANR") of municipal town roads and related road infrastructure. Also attached are aerial maps of the Road Segments and the locations of drop outlets along the roadways

The aerial maps are available for viewing by signing in on the ANR's website: <a href="http://anrmaps.vermont.gov/websites/anra5/">http://anrmaps.vermont.gov/websites/anra5/</a> and searching for the project titled "Lake Rescue Drainage".

Attached as Exhibit B are photographs of some of the damage observed after the storm on April 14, 2019.

The Lake Rescue Association would like to meet to discuss this request and assist the Town in gathering any additional information it may need to complete this work in as expeditious a timeframe as possible.

LRA Board member Kevin Golmont will contact you to arrange a time to discuss. We look forward to partnering with the Town of Ludlow to solve this pressing issue.

Sincerely,

Barb Silver and Bruce Zanca, Co-Presidents On behalf of the Lake Rescue Association

## **EXHIBIT A**

Drop Inlet and Road Segment Inventory Lakes Region Town of Ludlow

97894 Road Segment

97891 Road Segment

502653

502650

RSID	Description	Object ID	RSID De	scription	Object ID		
Ellisons Lake	Road, North of Fishi	ng Access Road Road #32082	East Lake Road from P	East Lake Road from Pettinger Hill Road to Red Bridge Road Road #32080			
95367	Road Segment	498391	94002 Road Seg	gment	494924		
95368	Road Segment	498392	94002 Drop inle	et	38486		
95368	Drop Inlet	24383	94003 Road Seg	gment	494925		
95369	Road Segment	498393	94004 Road Seg	gment	494926		
95369	Drop Inlet	78225	94004 Road Seg	gment	37571		
95370	Road Segment	498394	94005 Road Seg	gment	494927		
95371	Road Segment	498395	94006 Road Seg	gment	494928		
95371	Drop Inlet	50876	94007 Road Seg	gment	494929		
			94007 Drop Inle	et	64164		
Ellisons Lake	Road South to East L	ake Road #32082	94007 Drop Inle	et	75525		
95372	Road Segment	498396	94007 Drop Inle	et	37784		
95372	Drop Inlet	45142	94008 Road Seg	ment	494930		
95373	Road Segment	498397	94009 Road Seg	gment	494931		
95374	Road Segment	498398	94009 Drop Inle	et	10656		
95374	Drop Inlet	55729	94010 Road Seg	ment	494932		
95375	Road Segment	498399	94011 Road Seg	ment	494933		
95375	Drop Inlet	65915	94011 Drop Inle	et	40638		
95376	Road Segment	498400	94011 Bridge		16		
95377	Road Segment	498401	94012 Road Seg	gment	494934		
95377	Drop Inlet	15574	94012 Drop Inle	et	68673		
95377	Drop inlet	13743	93976 Road Seg	gment	494902		
95378	Road Segment	498402	93977 Road Seg	gment	494206		
95378	Drop Inlet	52869	93977 Drop Inle	et .	45213		
95378	Outfall	182344	93978 Road Seg	gment	494207		
95365	Road Segment	498389	93978 Drop Inle	et .	4625		
95365	Bridge	30377	93978 Drop Inle	et .	63939		
95365	Catch Basins	Not Listed in Inventory	93979 Road Seg	ment	494208		
			93979 Drop Inle	et	55879 This	Drop Inlet feeds stream to a Drop Inlet East of	
Fishing Acces	ss Road		93980 Road Seg	gment	494186	Archibald Lane and running under the lane	
97892	Road Segment	502651	_			Not on ANR Atlas	
97892	Pipe under driveway		Tepper Drive				
97893	Road Segment	502652	There are several ditch	nes and inlet	to be addressed		
97893	Drop Inlet	96257	Not on ANR Atlas				
	- 1-						

## **EXHIBIT A**

Drop Inlet and Road Segment Inventory Lakes Region Town of Ludlow

97894 Road Segment

97891 Road Segment

502653


502650

RSID	Description	Object ID	RSID De	scription	Object ID		
Ellisons Lake	Road, North of Fishi	ng Access Road Road #32082	East Lake Road from P	East Lake Road from Pettinger Hill Road to Red Bridge Road Road #32080			
95367	Road Segment	498391	94002 Road Seg	gment	494924		
95368	Road Segment	498392	94002 Drop inle	et	38486		
95368	Drop Inlet	24383	94003 Road Seg	gment	494925		
95369	Road Segment	498393	94004 Road Seg	gment	494926		
95369	Drop Inlet	78225	94004 Road Seg	gment	37571		
95370	Road Segment	498394	94005 Road Seg	gment	494927		
95371	Road Segment	498395	94006 Road Seg	gment	494928		
95371	Drop Inlet	50876	94007 Road Seg	gment	494929		
			94007 Drop Inle	et	64164		
Ellisons Lake	Road South to East L	ake Road #32082	94007 Drop Inle	et	75525		
95372	Road Segment	498396	94007 Drop Inle	et	37784		
95372	Drop Inlet	45142	94008 Road Seg	ment	494930		
95373	Road Segment	498397	94009 Road Seg	gment	494931		
95374	Road Segment	498398	94009 Drop Inle	et	10656		
95374	Drop Inlet	55729	94010 Road Seg	ment	494932		
95375	Road Segment	498399	94011 Road Seg	ment	494933		
95375	Drop Inlet	65915	94011 Drop Inle	et	40638		
95376	Road Segment	498400	94011 Bridge		16		
95377	Road Segment	498401	94012 Road Seg	gment	494934		
95377	Drop Inlet	15574	94012 Drop Inle	et	68673		
95377	Drop inlet	13743	93976 Road Seg	gment	494902		
95378	Road Segment	498402	93977 Road Seg	gment	494206		
95378	Drop Inlet	52869	93977 Drop Inle	et .	45213		
95378	Outfall	182344	93978 Road Seg	gment	494207		
95365	Road Segment	498389	93978 Drop Inle	et .	4625		
95365	Bridge	30377	93978 Drop Inle	et .	63939		
95365	Catch Basins	Not Listed in Inventory	93979 Road Seg	ment	494208		
			93979 Drop Inle	et	55879 This	Drop Inlet feeds stream to a Drop Inlet East of	
Fishing Acces	ss Road		93980 Road Seg	gment	494186	Archibald Lane and running under the lane	
97892	Road Segment	502651	_			Not on ANR Atlas	
97892	Pipe under driveway		Tepper Drive				
97893	Road Segment	502652	There are several ditch	nes and inlet	to be addressed		
97893	Drop Inlet	96257	Not on ANR Atlas				
	- 1-						

### Drop Inlet and Road Segment Inventory Lakes Region Town of Ludlow

RSID	Description	Object ID		RSID	Description	Object ID	
Red Bridge Road (from East to West)				East Lake Road, South of Red Bridge Road (Continued)			
53010.1 F	Road Segment	591394 Not H	lydrologically connected	93987	Drop Inlet	36789	
53011.11 F	Road Segment	591198 Not H	lydrologically connected	93987	Drop Inlet	72485	
53012.1 F	Road Segment	591199		93988	Road Segment	494910	
53013.1 F	Road Segment	591299		93989	Road Segment	494911	
53014.1 F	Road Segment & Bridge	591201		93989	Drop Inlet	8142	
53015.1 F	Road Segment	591202		93989	Drop Inlet	92318	
53015.1	Orop Inlet	65405		93990	Road Segment	494912	
53008.1 F	Road Segment	591197		93990	Drop Inlet	6997	
				93991	Road Segment	494913	
Spruce Lane				93991	Drop Inlet	68455	
170620 F	Road Segment	614012		93991	Drop Inlet	58201	
170620 [	Orop Inlet	1267		93992	Road Segment	494914	
170623 F	Road Segment	614015		93993	Road Segment	494915	
170623 [	Orop Inlet	22832		93993	Drop Inlet	44235	
170622 F	Road Segment	614014		93994	Road Segment	494916	
170621 F	Road Segment	614013		93944	Drop Inlet	25831	
182198 F	Road Segment	629471		93995	Road Segment	494917	
182187 F	Road Segment	629470			Drop Inlet	44000	
					Road Segment	494918	
East Lake Road, South of Red Bridge Road				Drop Inlet	88399		
	Road Segment	494903			Road Segment	494919	
	Road Segment	494904			Drop Inlet	53169	
	Orop Inlet	93938		93975	Road Segment	494901	
	Road Segment	494905					
	Orop Inlet	34501		Lake Pauline			
	Road Segment	494906			Road Segment	537049	
	Road Segment	494907			Drop Inlet	39973	
	Orop Inlet	10545			Road Segment	537053	
	Orop Inlet	90257			Road Segment	537052	
	Road Segment	494908			Road Segment	537051	
	Orop Inlet	91418		122183	Drop Inlet	14343	
	Orop Inlet	13473		_			
93987 F	Road Segment	494909		Carpenter's I			
					Drop Inlet	71620	
				18514	Road Segment		








**EXHIBIT B** 

Overflowing stream crossing Archibald Lane, April 15,2019



# **EXHIBIT B**

Clogged inlet at the intersection of Ellison's Lake Road and Fishing Access Road, April 19, 2019



# **EXHIBIT B**

Erosion at intersection of Ellison's Lake Road and Fishing Access Road from run off caused by clogged inlet, April 19, 2019

